

**From:** [Warren D Fusilier](#)  
**To:** [Gary Moore/R6/USEPA/US@EPA](#)  
**Subject:** RE: Falcon Refinery  
**Date:** 08/23/2010 01:35 PM  
**Attachments:** [100\\_0749.jpg](#)

---

I meant to include the attached picture:

<<100\_0749.jpg>>

[Warren D. Fusilier](#)

[Office - 713-646-4515](#)

---

**From:** Warren D Fusilier  
**Sent:** Monday, August 23, 2010 1:31 PM  
**To:** 'moore.gary@epa.gov'  
**Subject:** Falcon Refinery

Gary,

I tried to call back a couple of times but go directly to your voice mail so I figured I would send an email. Plains Marketing, LP has a terminal that is adjacent to the Falcon Refinery site. On the Plains property there are a couple of pipes that originate across the fence and onto the Falcon site, come under Plains fence and then come above ground, where they are flanged off. Near one of the pipes a stain has started to develop and appears to be getting larger. We are looking for guidance on how you would want to investigate further what is occurring. My contact information is below.

Warren D. Fusilier

Director Environmental and Regulatory Compliance, GC

Plains All American Pipeline, LP

333 Clay Street, Suite 1600

Houston, Texas 77002

Office - 713-646-4515

Cell - 713-201-3911

Fax - 713-646-4310

Rightfax - 713-289-7621



9567287